

-2-47

Sp. St. 2 x 16

E 200-3-169

Sp. St. 3 x 12

E 200-3-242

E 200-3-243

E 200-3-235

-188

F 3 x 10

E 200-3-168

-3-165

Sp. St. 3 x 12

E 200-3-220

-3-39

Sp. St. 3 x 12

E 200-3-227

-3-208 (M)

Sp. St. 3 x 12

E 200-3-234

-3-210

Sp. St. 3 x 12

F 200-3-221

5 x 15

Sp. St. 3 x 12

F 200-3-167

Lagernadel 2 x 118

D 200-3-209

D 19 φ 6

E 200-3-166

Schnitt G-G